

MCXN23x_0P21K

Mask Set Errata



Mask Set Errata for Mask 0P21K

Revision History

This report applies to mask 0P21K for these products:

- MCXN236VDFT
- MCXN236VNLT
- MCXN235VNLT
- MCXN235VDFT

Table 1. Revision History

Revision	Date	Significant Changes
1.0	5/2024	Initial Revision

Errata and Information Summary

Table 2. Errata and Information Summary

Erratum ID	Erratum Title
ERR050875	CoreSight: AHB-AP can issue transactions where HADDR[1:0] is not aligned to HSIZE on the AHB
ERR051421	SAI: Synchronous mode with bypass is not supported
ERR051588	LPSPi:Reset transmit FIFO after FIFO underrun by LPSPi Slave.
ERR051617	I3C: In I2C compatibility mode read transaction not terminating correctly
ERR051629	LPUART:Transmit Complete bit (STAT[TC]) is not set.
ERR051704	DCDC: Failure changing to Low drive-strength mode
ERR051713	ADC: Extra conversion can occur when moving to low power mode
ERR051874	I2C clock stretching mode is not supported
ERR051989	PWM: output may be abnormal when the value of phase delay register is reduced from a non-zero value to 0.
ERR051998	ROM: Command "get-property 12" not supported when using USB interface
ERR052108	ROM: LDO_SYS VDD level not returned to Normal voltage range after programming fuses
ERR052122	I3C : Data size limitation in Message mode DDR transfer
ERR052147	USB: ISO schedule issue in FS Host mode
ERR052241	CDOG: Restart command can't let timer count down

Known Errata

ERR050875: CoreSight: AHB-AP can issue transactions where HADDR[1:0] is not aligned to HSIZE on the AHB

Description

ARM errata 1624041

This erratum affects the following components:

- AHB Access Port.

The ARM Debug Interface v5 Architecture Specification specifies a TAR (Transfer Address Register) in the MEM-AP that holds the memory address to be accessed.

TAR[1:0] is used to drive HADDR[1:0] when accesses are made using the Data Read/Write register DRW.

When the AHB-AP is programmed to perform a word or half-word sized transaction the AHB-AP does not force HADDR[1:0] to be aligned to the access size. This can result in illegal AHB transactions that are not correctly aligned according to HSIZE if HADDR[1:0] is programmed with an unaligned value.

Conditions:

- 1) TAR[1:0] programmed with a value that is not aligned with the size programmed in the CSW register of the AHB-AP.
- 2) An access is initiated by an access to the Data Read/Write Register (DRW) in the AHB-AP.

Implications:

As a result of the programming conditions listed above, AHB-AP erroneously initiates an access on the AHB with HADDR[1:0] not aligned to the size on HSIZE. This might initiate an illegal AHB access.

Workaround

TAR[1:0] must be b00 for word accesses, TAR[0] must be b0 for half-word accesses.

Software program should program TAR with an address value that is aligned to transaction size being made.

ERR051421: SAI: Synchronous mode with bypass is not supported

Description

The SAI does not receive or transmit when:

Scenario 1. The transmitter is configured for synchronous mode (TCR2[SYNC] = 0b1), in the Transmit Configuration 2 register, and the receiver is in bypass (RCR2[BYP]=0b1), in the Receiver Configuration 2 register, then there will not be a bit clock as it is the source of the BCLK.

Scenario 2. The receiver is configured for synchronous mode (RCR2[SYNC] = 0b1) in the Receiver Configuration 2 register and the transmitter is in bypass (TCR2[BYP]=0b1), in the Transmit Configuration 2 register, then there will not be a bit clock as it is the source of the BCLK.

Workaround

If scenario 1, then set the TCR2[BCI] = 0b1, in the Transmit Configuration 2 register.

If scenario 2, then set the RCR2[BCI] = 0b1, in the Receiver Configuration 2 register.

ERR051588: LPSPI:Reset transmit FIFO after FIFO underrun by LPSPI Slave.

Description

Transmit FIFO pointers are corrupted when a transmit FIFO underrun occurs (SR[TEF]) in slave mode.

Workaround

When clearing the transmit error flag (SR[TEF] = 0b1) following a transmit FIFO underrun, reset the transmit FIFO (CR[RTF] = 0b1) before writing any new data to the transmit FIFO.

ERR051617: I3C: In I2C compatibility mode read transaction not terminating correctly

Description

The I3C module can operate in I2C compatibility mode to support I2C devices. However when operating in this mode, the end of any read transaction may terminate with a repeated START followed by the STOP instead of only a STOP.

Workaround

In I2C compatibility mode, the use of no skew should be avoided and must set to MCONFIG[SKEW] = 1.

ERR051629: LPUART:Transmit Complete bit (STAT[TC]) is not set.

Description

When the CTS pin is negated and the CTS feature is enabled (MODIR[TXCTSE] = 0b1) and the TX FIFO is flushed by software then, the Transmit Complete (STAT[TC]) flag is not set.

Workaround

Clear (MODIR[TXCTSE]) bit and reset the transmit FIFO (FIFO[TXFLUSH] = 0b1) when flushing the FIFO with CTS enabled(MODIR[TXCTSE] = 0b1).

ERR051704: DCDC: Failure changing to Low drive-strength mode

Description

The DCDC output may fail when transitioning from Normal to Low drive-strength, resulting in the DCDC output voltage dropping to the point it is not able to adequately power the VDD_CORE supply, or causes temporary brown-out conditions. This failure may occur when both of these conditions occur:

- 1) The transition from Normal drive strength (DCDC_VDD_DS = 10b) to Low drive-strength (DCDC_VDD_DS = 01b) occurs when the DCDC is actively switching the output.
- 2) The voltage level set in the bitfield SPC->LP_CFG[DCDC_VDD_LVL] is greater than or equal to the current output voltage of the DCDC.

Because this failure requires a specific timing to manifest, it may fail very infrequently in an application. The greater the load current of the DCDC, the more likely the failure will occur because the DCDC will spend more time in the active switching period. A higher rate of transitioning to Low drive-strength will also see a higher failure rate.

There are two scenarios when the DCDC drive-strength can transition from Normal to Low drive-strength, and this failure may occur:

- 1) While the MCU is in Active power mode, and the application changes the drive-strength setting by writing 01b to the bitfield SPC->ACTIVE_CFG[DCDC_VDD_DS]. Writing this bitfield will start the transition to Low drive-strength.

2) When the MCU enters a low-power mode (Deep Sleep, Power Down, or Deep Power Down), and Active mode uses Normal drive-strength with `ACTIVE_CFG[DCDC_VDD_DS] = 10b`, while the low-power mode uses Low drive-strength with `LP_CFG[DCDC_VDD_DS] = 01b`.

Workaround

This issue will always be avoided when the voltage level at the low-power low drive-strength is lower than the current output voltage of the DCDC. Before transitioning to Low drive-strength, ensure the voltage level in `LP_CFG[DCDC_VDD_LVL]` is lower than the voltage level in Normal drive-strength configured by `ACTIVE_CFG[DCDC_VDD_LVL]`. As part of this workaround, the voltage level used in Low drive-strength configured by `LP_CFG[DCDC_VDD_LVL]` must not be set to the maximum value `11b` for 1.2 V at any time in an application.

If the desired voltage level in `LP_CFG[DCDC_VDD_LVL]` is the same as the level currently set in `ACTIVE_CFG[DCDC_VDD_LVL]`, a workaround is to temporarily increase the voltage level in `ACTIVE_CFG[DCDC_VDD_LVL]`, and then transition to Low drive-strength with the lower level in `LP_CFG[DCDC_VDD_LVL]`. Here is the sequence for this workaround:

- 1) Ensure `LP_CFG` is configured for Low drive-strength and the desired voltage level in Low drive-strength mode
- 2) Wait for the SPC bit `SC[BUSY]` to be clear.
- 3) Write `ACTIVE_CFG[DCDC_VDD_LVL]` with the value for the voltage level one step higher than the desired level in `LP_CFG[DCDC_VDD_LVL]`.
- 4) Start the transition to Low drive-strength

If the workaround sequence above is used when the MCU enters a low-power mode, then when the MCU wakes the DCDC will return to Normal drive-strength with the output voltage level configured in `SPC->ACTIVE_CFG[DCDC_VDD_LVL]`. If a lower voltage level is preferred, the application can lower DCDC voltage by waiting for the bit `SC[BUSY]` to be clear and writing the new voltage level to `SPC->ACTIVE_CFG[DCDC_VDD_LVL]`.

ERR051713: ADC: Extra conversion can occur when moving to low power mode

Description

When high-priority trigger exceptions are enabled (`ADCx->CFG[HPT_EXDI] = 0x1`) and the ADC command uses the "Repeat until true" compare option (`ADCx->CMDHa[CMPEM] = 0x3`), an extra conversion occurs at the end of the conversion cycle if a higher priority trigger is asserted when a low power request is also made. This can result in erroneous extra data in the result FIFO and/or prevent the ADC module from being disabled in the low power mode (even if the Doze enable bit is set - `ADCx->CTRL[DOZEN] = 0x1`).

Workaround

The ADC workaround is to do ONE of the following:

- Disable the ADC before entering low power mode (`ADCx->CTRL[ADCEN] = 0`)
- Disable high priority exceptions (`ADCx->CFG[HPT_EXDI] = 0x1`)
- If high priority exceptions are enabled (`ADCx->CFG[HPT_EXDI] = 0x1`) and "Repeat until true" compare option is used (`ADCx->CMDHa[CMPEM] = 0x3`), then the trigger command select (`ADCx->TCTRLa[TCMD]`) pointing to that command must be the highest priority (`ADCx->TCTRLa[TPRI] = 0`).
- User software waits for final conversion to be completed before entering low power mode.

ERR051874: I2C clock stretching mode is not supported

Description

I3C IP when working as I2C master mode it doesn't support Clock stretching feature.

Workaround

Application must not use I2C clock stretching feature. It will create clock contention on bus.

I2C Targets on the bus must keep Clock stretching feature disabled.

ERR051989: PWM: output may be abnormal when the value of phase delay register is reduced from a non-zero value to 0.

Description

When the value of the SMxPHASEDLY register is reduced from a non-zero value to 0 and the SMxCTRL2[RELOAD_SEL]=1, the submodule x may output an unexpected wide PWM pulse (x=1,2,3).

Workaround

The minimum value of the SMxPHASEDLY register should be set as 1 in this process. To realize no phase delay between the submodule 0 and submodule x in this process, set the SMxPHASEDLY=1, SMxINIT=SM0INIT-1, SMxVALy=SM0VALy-1 (x=1,2,3, y=0,1,2,3,4,5).

ERR051998: ROM: Command "get-property 12" not supported when using USB interface

Description

When using the USB interface to access the device in ISP mode, command "get-property 12" returns a fail result. This applies to both Full-Speed and High-Speed USB interfaces.

Workaround

There is no workaround for this issue. Customers should not use the "get-property 12" command when using USB as the ISP mode interface.

ERR052108: ROM: LDO_SYS VDD level not returned to Normal voltage range after programming fuses

Description

When programming any fuse using the ROM API, the voltage level of the LDO_SYS is not returned to Normal Voltage level (1.8V). That is, SPC0->ACTIVE_CFG[SYSLDO_VDD_LVL] = 1.

Workaround

User software should return the LDO_SYS voltage level to normal level immediately after programming fuses (SPC0->ACTIVE_CFG &= ~SPC_ACTIVE_CFG_SYSLDO_VDD_LVL_MASK;).

Note that the SDK functions which program fuses already account for this errata.

ERR052122: I3C : Data size limitation in Message mode DDR transfer

Description

The message length in DDR message(DMA) mode is defined in MWMSG_DDR_CONTROL2 [9:0].LEN field. The 2 MSBs [9:8] of this field has no effect on operation. Only [7:0] part of this field is taken as length in number of Half words. So, for max value of 3FF h in this field is taken as FF h (255) by hardware , consequently the maximum amount of actual data gets limited as per the operation type. For Read operation the actual data size will be (255 - 2) = 253 half-words (506 bytes) and for write operation it is (255 -1) = 254 halfword (508 bytes)

Workaround

Application need to limit the data size for Write and Read operation in message(DMA) mode of DDR transfer. Configure MWMSG_DDR_CONTROL2 [9:0].LEN = FF h, For Read frame data receive size will be 506 bytes and for Write frame data transmit size will be 508 bytes for a single frame.

ERR052147: USB: ISO schedule issue in FS Host mode**Description**

When working in FS Host mode, for ISO communication, if the first ISO package is equal or greater than about 238 bytes, then the second ISO transaction could not be scheduled in the same 1 ms frame.

For example, a typical application case affected is audio bi-directional communication with 48 KHz sample rate, 24 bit per sample and 2 channels for both direction. In this case, we need one ISO IN 288 bytes (>238 bytes) + one ISO OUT 288 bytes (>238 bytes) in one 1 ms frame. But actually, only one ISO OUT 288 bytes or only one ISO IN 288 bytes is available in one 1 ms frame due to the IP limitation.

Workaround

No workaround.

ERR052241: CDOG: Restart command can't let timer count down**Description**

Due to this errata, once RESTART command is written to RESTART register, the Instruction Timer is continually reloaded with the value in the RELOAD register and the counter will not count down (until subsequent accesses of CDOG registers).

Workaround

Replace RESTART register write instructions in all locations with a write to the STOP register immediately followed by a write to the RELOAD and START register. Both the STOP and START registers should be written with the same value in this situation..

Legal information

Definitions

Draft — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

Disclaimers

Limited warranty and liability — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

Right to make changes — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

Suitability for use — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

Applications — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

Terms and conditions of commercial sale — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at <https://www.nxp.com/profile/terms>, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

Export control — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

Suitability for use in non-automotive qualified products — Unless this document expressly states that this specific NXP Semiconductors product is automotive qualified, the product is not suitable for automotive use. It is neither qualified nor tested in accordance with automotive testing or application requirements. NXP Semiconductors accepts no liability for inclusion and/or use of non-automotive qualified products in automotive equipment or applications.

In the event that customer uses the product for design-in and use in automotive applications to automotive specifications and standards, customer (a) shall use the product without NXP Semiconductors' warranty of the product for such automotive applications, use and specifications, and (b) whenever customer uses the product for automotive applications beyond NXP Semiconductors' specifications such use shall be solely at customer's own risk, and (c) customer fully indemnifies NXP Semiconductors for any liability, damages or failed product claims resulting from customer design and use of the product for automotive applications beyond NXP Semiconductors' standard warranty and NXP Semiconductors' product specifications.

Translations — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

Security — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately. Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at PSIRT@nxp.com) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

NXP B.V. — NXP B.V. is not an operating company and it does not distribute or sell products.

Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

NXP — wordmark and logo are trademarks of NXP B.V.

AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, μ Vision, Versatile — are trademarks and/or registered trademarks of Arm Limited (or its subsidiaries or affiliates) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved.

MCX — is a trademark of NXP B.V.

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

© NXP B.V. 2024.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: salesaddresses@nxp.com

Date of release: 5/2024

Document identifier: MCXN23x_0P21K