PTN3944EVM-KIT
Packing Instructions

Bill of Materials

Reference Agile BOM 975-47873

Agile PN	Description	Qty	Packed by:
700-47770	PWA, X-PTN38007-BASE	1	CM
700-47772	PWA, X-PTN3944EVM	1	CM
925-47873	PACKING LIST, PTN3944EVM-KIT	1	CM
924-76425	QUICK START GUIDE, ANALOG TOOLS	1	CM
600-77561	CABLE, 10-Pin Socket /Socket IDC Cable	1	CM
600-77562	CABLE, USB-A to DC 5.5 x 2.1mm DC 5V Power Plug	1	CM
805-77462	LABEL, PQ	1	CM
805-75208	LABEL, CE MARK	1	CM
590-46094	FOAM,FOR ICC-QMC-DGC BOARD USE WITH 570-46093 BOX	1	CM
570-46094	BOX, E-FLUTE (WHITE), 100x55x55mm	1	CM
Vendor's Choice	ESD STATIC SHIELDING BAG	1	CM
Vendor's Choice	PINK BUBBLE WRAP	AR	CM

Step 1 –
Assemble both two boards(Board-1:**700-47770** and Board-2:**700-47772**) and place into an ESD Static Shielding as shown:

Pictures are use as reference image only

Step 2 -
Wrap the board with Pink bubble wrap. Use enough so that the board is not loose in the box.


Pictures are use as reference image only

Step 3 –

Place the FOAM (590-46094) inside box and then Securely place the assembled board and cables(600-77561 and 600-77562) inside box(570-46094) as shown:

PCBA

CABLES (600-77561)
and (600-77562)

Pictures are use as reference image only

Step 4 –

Place QUICK START GUIDE, ANALOG TOOLS(924-76425) by folding to accommodate inside the box

Place Packing List (925-47873) on top as shown:

Pictures are use as reference image only

Step 5 –
Close the box and apply PQ label (805-77462) on top side as shown below:

Pictures are use as reference image only

Step 6 –
Stick CE Mark (805-75208) on top side as shown below:

Pictures are use as reference image only

This completes pack out