

Certification date: Expiry date: Certificate number: IATF Certificate number: 11 December 2023 10 December 2026 10575096 0491454

Certificate of Approval

This is to certify that the Management System of:

NXP USA, Inc.

Austin Technology & Manufacturing Center, 3501 Ed Bluestein Boulevard, Austin, TX, 78736,

IATF USI: Y3ZWK2

has been approved by LRQA to the following standards:

IATF 16949:2016

Approval number(s): IATF 16949 - 0077983-001 Corporate Scheme Identifier: UQA00000767

This certificate is valid only in association with the certificate schedule bearing the same number on which the locations applicable to this approval are listed.

The scope of this approval is applicable to:

Design and Manufacture of Semiconductors.

Marta Escudero

Regional Director, United Kingdom and Americas (UKAM)

Issued by: LRQA Limited

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.



0077983-001 10575096 0491454

Certificate Schedule

Remote Support Location

NXP USA, Inc

1300 North Alma School Road, Chandler Fab, AZ, 85224, **United States**

IATF USI: 63F633

Location

Remote Support Location

NXP Semiconductors Malaysia, Kuala Lumpur Final Manufacturing

Jalan SS 8/2, Sungai Way, Free Trade Zone, Petaling Jaya, 47300 Kuala Lumpur, Malaysia

IATF USI: 6KASEK

Remote Support Location

NXP (China) Management Ltd

Floor 1-3, Building 10, Jintai Intelligent Industrial Park, No. 22 Jinyu Avenue, Liangjiang New District, Chongqing 400014, China

IATF USI: GKN6E9

Remote Support Location

NXP USA, Inc

6501 William Cannon Drive West, Austin, TX, 78735, United States

IATF USI: 32FARF

Remote Support Location

NXP Semiconductors Austria GmbH

Mikron-Weg 1, A-8101 Gratkorn, Steiermark, Austria

IATF USI: LAR53S

Remote Support Location

NXP Semiconductors Canada Ltd.

1 Hines Road, Kanata, ON K2K 3C7 Hines Road, Kanata, On, K2K 3C7, Canada

IATF USI: T4RYXX

IATF 16949:2016

Activities

Product Design.

IATF 16949:2016

Product Design.

IATF 16949:2016

After Sales.

IATF 16949:2016

Product Design and Quality System Management.

IATF 16949:2016

Product Design; Aftersales; Human Resource; Marketing.

IATF 16949:2016

Product Design.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract. Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



0077983-001 10575096 0491454

LRQA

LRQA

10/20/2009

LPOA

LDOA

LRQA

LRQ/

LRQ/

LRQ/

LRQ/

LRQA

LRQ/

LRQ/\

LRQ/

500

LRQ/

LRQ/

LRQ/

LRQ/

Certificate Schedule

Remote Support Location

NXP (China) Management Ltd

No. 118 Jianguo Road, 23rd Floor Exchange Building, Beijing, Chaoyang District 100022, China

IATF USI: L4CMCZ

Remote Support Location

NXP (China) Management Ltd.

No. 192 Liangjing Road, Pudong New Area, Shanghai 201203,

China

Location

IATF USI: 35C4NY

Remote Support Location

NXP (China) Management Ltd.

No. 288, Zhuyuan Road, New District, Suzhou City, Jiangsu Province P.R.C 215011, China

IATF USI: 65CRX6

Remote Support Location

NXP Semiconductors (Tianjin) Ltd

No.9 Weiwu Road, Micro-electronics Industrial Park, XiQing Dist, Tianjin 300085, China

IATF USI: LXKC5E

Remote Support Location

NXP Qiangxin (Tianjin) IC Design Co., Ltd.

No. 80, 4th Avenue, High-Tech Park F3 Ste A1, Teda, Tianjin P.R.C 300457, China

IATF USI: 3CRT5C

Remote Support Location

NXP Semiconductors (Tianjin) Ltd

No. 15 Xinghua Avenue, Xiquing Economic Development Area,

Tianjin City 300385, China

IATF USI: 65CXPN

IATF 16949:2016

Product Design.

Activities

IATF 16949:2016 Product Design.

IATF 16949:2016

IATF 16949:2016

IATF 16949:2016

IATF 16949:2016

Product Design.

Testing.

Product Design.

Product Design, Human Resource.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



0077983-001 10575096 0491454

Page 4 of 8

Certificate Schedule

Remote Support Location

Shanghai (BMIC) - Puxi

19F, 20F, and 21F BM InterContinental Business Center, 100 Yu Tong Rd., Shanghai 200070, China

IATF USI: Y5CH5G

Location

Remote Support Location

NXP Semiconductors Czech Republic s.r.o.

1.máje 1009, Rožnov pod Radhoštěm, 756 61 Roznov, Czech Republic

IATF USI: PARMZ6

Remote Support Location

NXP Semiconductors Czech Republic s.r.o.

Sochorova 3232, 616 00 Brno-Žabovřesky, Czech Republic

IATF USI: C4R3Y5

Remote Support Location

NXP Semiconductors France SAS

134 Avenue du Général Eisenhower, B.P. 72329, 31023

Toulouse, France IATF USI: T9RWS9

Remote Support Location

NXP Semiconductors Germany GmbH

Schatzbogen 7, 81829 Munich, Germany

IATF USI: L3RNLZ

Remote Support Location

NXP Semiconductors Germany GmbH

Prager Strasse 2a, 01069 Dresden, Germany

IATF USI: T2RKMA

Activities

IATF 16949:2016 Sales, After Sales.

IATF 16949:2016

Product Design, Customer Service, Human Resources.

IATF 16949:2016 Product Design.

IATF 16949:2016

Product Design.

IATF 16949:2016

Product Design; Aftersales; Sales; Marketing.

IATF 16949:2016

Product Design.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract. Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



0077983-001 10575096 0491454

LRQA

LRQA

LRQA

LRQ/

LRQA

LRQA

LRQ/

LRQ/

LRQ/

.

LRQA

LRQ/

LRQA

LRQ/

LRQ/

Certificate Schedule

Remote Support Location

NXP Semiconductors Germany GmbH

Beiersdorfstrasse 12, 22529 Hamburg, Germany

IATF USI: G3RCF6

Location

Activities

Product Design; Aftersales; Human Resource; Marketing;

Contract Review.

IATF 16949:2016

Remote Support Location

NXP Semiconductors Hungary Ltd.

Buddafoki Ut 91-93, 1117 Budapest, Hungary

IATF USI: T4R9F4

IATF 16949:2016

After Sales.

Remote Support Location

NXP India Pvt Ltd

Plot No. 2 & 3 & 18, Sector 16A, Noida, 201301, Uttar Pradesh,

India

IATF USI: L6R5KH

IATF 16949:2016 Product Design.

Remote Support Location

NXP Semiconductors India Pvt. Ltd.

1st Floor, Block-3, DLF Cyber City, Plot No. 129 to 132, APHB

Colony, Gachibowli, Hyderabad, 500019, India

IATF USI: G5RR3P

IATF 16949:2016

Product Design.

Remote Support Location

NXP Semiconductors India Pvt Ltd.

Information Technology Park, Nagawara Village Kasaba Hobli,

Bangalore, IND-560 045, India

IATF USI: L3RZ35

IATF 16949:2016 Product Design.

Dometa Cumport I and

Remote Support Location

NXP Japan Ltd.

Yebisu Garden Place Tower 24F, 4-20-3 Ebisu, Shibuya-ku,

Tokyo 150-6024, Japan

IATF USI: C4L3S5

IATF 16949:2016

Sales, After Sales, Marketing.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract. Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



0077983-001 10575096 0491454

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract. Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Certificate Schedule

Remote Support Location

NXP Semiconductors Netherlands BV

Elekronicaweg 40, 2628 Delft, The Netherlands

IATF USI: C4RL3A

Location

Activities IATF 16949:2016

Product Design.

Remote Support Location

NXP Semiconductors Netherlands B.V.

High Tech Campus, 5656 AG Eindhoven, The Netherlands

IATF USI: P4RY3S

IATF 16949:2016

Product Design; Information Technology.

Remote Support Location

NXP Semiconductors Netherlands B.V

Gerstweg 2, 6534 AE Nijmegen, The Netherlands

IATF USI: LSAGPH

IATF 16949:2016

Product Design.

Remote Support Location

NXP Semiconductors Singapore Pte Ltd

1 Fusionopolis Walk, #02-11, North Tower, Solaris 138628,

Singapore

IATF USI: 6MAEEW

IATF 16949:2016

Sales, Marketing, Purchasing, After Sales, Supplier Management, Process Design.

NXP Semiconductors Nordic AB

Remote Support Location

Kronborgsgrand 19, SE-164 46 Kista, Sweden

IATF USI: P5RKKS

IATF 16949:2016

Product Design.

Remote Support Location

NXP Semiconductors Taiwan Ltd.

6F-6, 7F, No. 66, San Chong Road, Nan Gang District, Taipei

11501, Taiwan

IATF USI: LEH9LW

IATF 16949:2016

Sales, After Sales.



Sales, After Sales; Supplier Management.

0077983-001 10575096 0491454

LRQA

LRQA

LPOA

LRQA

LRQA

LRQ/

LRQ/

LRQA

LRQ/

LRQA

LRQA

LRQ/\

LRQ/

Sile

LRQA

LRQA

LRQ/

Certificate Schedule

Remote Support Location

NXP Semiconductors Taiwan Ltd

4F, No. 19-8, San Chong Road, Nan Gang District, Taipei 11501, Taiwan

IATF USI: PCHRYX

Location

Remote Support Location

NXP Semiconductors Taiwan Ltd.

No. 10, Jing 5th Rd., Nanzi Dist., Kaohsiung City 81170, Taiwan

IATF USI: CFH4XP

Remote Support Location

NXP Semiconductors Taiwan Ltd.

9F, 10F, San Chong Road, Nan Gang District, Taipei 11501,

Taiwan

IATF USI: CEHZLW

Remote Support Location

NXP Laboratories UK Ltd

Pegasus House, 3 Bramah Avenue, Scottish, Enterprise Technology Park, East Kilbride, Glasgow, G75 0RD, Scotland, United Kingdom

IATF USI: T4RMX9

Remote Support Location

NXP Laboratories UK Ltd

The Cattle Barn, Upper Ashfield Farm, Hoe Lane, Romsey, Southampton, S051 9NJ, United Kingdom

IATF USI: Y4RPMN

Remote Support Location

NXP Manufacturing (Thailand) Ltd

303 Moo 3 Chaengwattana Road, Bangkok, 10210, Thailand

IATF USI: P6MYNC

IATF 16949:2016

Customer Service, Logistics.

Activities

IATF 16949:2016

IATF 16949:2016 Product Design.

IATF 16949:2016
Product Design, Human Resources, and After Sales.

IATF 16949:2016 Product Design.

IATF 16949:2016

Product Design.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom



Location

Mexico

IATF USI: G9RMM4

IATF USI: T4R66S

Remote Support Location

Remote Support Location

061103 Bucharest, Romania

NXP Semiconductor Romania SRL

NXP Semiconductors Mexico S de RL de CV

Perferico Sur 8110, Col. El Mante, Tlaquepaque, 45609 Jalisco,

6L Iuliu Maniu boulevard, Campus 6.1 Building, District 6,

Certificate Schedule

Approval number(s): Certificate number: IATF Certificate number:

Product Design, Customer Service, Human Resource,

Activities

IATF 16949:2016

IATF 16949:2016

Information Technology.

Product Design, After Sales.

0077983-001 10575096 0491454

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Issued by: LRQA Limited, 1 Trinity Park, Bickenhill Lane, Birmingham B37 7ES, United Kingdom

Page 8 of 8